

Photo Report

Ventilation Unit — Pre-Work Check

Generated 5 Sep 2026 at 17:50

1200 Market Street Wilmington, DE 19801 United States

+1 (302) 555-0147 · contact@omniatics.com

<https://getprooflog.com>



Omniatics LLC




Photo record

Time: 26 Apr 2026 at 19:42

Location: Wilmington, Delaware, United States

GPS: 39,73910, -75,53980

Stage: Pre-Work

Note: Pre-work condition recorded for the ventilation unit and surrounding ductwork.

Verify duct connections, insulation, clearances, and service access before closing the area. Use this record for progress and final comparison.